BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Providing and laying HDPE water line in Mohankumar nagara Block 2 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2250/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/297/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,97,000/-
5	Job Code No.	017-14-000018
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/226/13-14 Dtd: 06.02.2014
8	Work order Number & Date	EE/RRND/WO/226/13-14 Dtd: 06.02.2014
9	Contract Amount as per Agreement	Rs. 53,46,612/-
10	Bill Amount	Rs. 43,75,200=25
11	B.R No. & Date	198/14-15 Dtd: 31.05.2014
12	Agency	M/s Damodar & Co.
13	M.B. Number & Page No. of Measurement records	118/13-14 Page No 11728 to 11734
14	Date of Inspection	05.09.2017
15	Enclosures	Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site along with the Concerned person, as per EE(RRND) Letter No EE (RRN) /PR/414/A/17-18 Dated 1-9-2017. It is observed that the Items indicated in the Xerox Copy of MB/ XL sheets are not suceptible for measurements, as such the photos taken during the execution of work have been scrutinised and Inspected, it appears that the above work has been done. This is a reference to the NOC Issued by Lokayukta vide Letter No LOK/INV(J)/CT/Crime/60/2014 Dated 1-8-2017

EE (RRN) Division, RR Nagara Zone.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು -

5/9/2017
(R. Sathyanarayana)
Inspection Report Officer.
R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner